August 18, 2003

TO: Internal File

THRU: Daron R. Haddock, Permit Supervisor

FROM: James D. Smith, Senior Reclamation Specialist

RE: 2003 First Quarter Water Monitoring, Energy West Mining Company, Trail

Mountain Mine, C/015/009-WQ03-1, Task ID #1349

- **1. Were data submitted for all of the MRP required sites?** YES [X] NO [] *Identify sites not monitored and reason why, if known*:
- 2. On what date does the MRP require a five-year resampling of baseline water data? See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

Resampling Due Date

Renewal submittal due 10/21/04, renewal due 02/21/05. Baseline analyses were performed in 1996, 2001 and will be repeated every 5 years, i.e., next baseline analyses will be in 2006.

3. Were all required parameters reported for each site? YES [X] NO [] Comments, including identity of monitoring site:

Page 2 C/015/009-WQ03-1 Task ID #1349 August 18, 2003

4. Were irregularities found in the data? Comments, including identity of monitoring site:	YES [X]	NO []
SW-2: sulfate $(n = 118)$ is outside the two standard	deviation range;		
5. Were DMR forms submitted for all required sites?			
	1 st month,	YES [X]	NO [
	2 nd month,	YES [X]	NO [
Identify sites and months not monitored:	3 rd month,	YES [X]	NO [
There was no discharge from either UPDES point do sealed in June 2001 and there has been no reported discharge mine-water dicharge into Cottonwood Creek) since May 20	ge at UPDES UT2		
6. Were all required DMR parameters reported? Comments, including identity of monitoring site:	YES [X]	NO []
There was no discharge from either UPDES point de	uring the first qua	rter.	
7. Were irregularities found in the DMR data?	YES[]	NO D	X 1

8. Based on your review, what further actions, if any, do you recommend?


Comments, including identity of monitoring site:

The Permittee needs to always confirm that for monitoring wells, water-depth and waterelevation values entered into the database are in feet rather than meters. Both water-depth and water-elevation need to be reported.

This is the sixth consecutive quarter SW-2 has had sulfate values outside two standard deviations. See the attached chart (2nd quarter 2003 is within two standard deviations.) The Permittee needs to identify the source of this increase in sulfate in the stream.

Page 3 C/015/009-WQ03-1 Task ID #1349 August 18, 2003

SW-2 Sulfate



O:\015009.TMT\WATER QUALITY\JDSWQ03-1.1349.DOC